


Metalurgia Primaria


TORPEDO

Pasek 80 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 S / G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 S	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 SIC 9 S	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 SIC 9 S	<input type="checkbox"/>	<input type="checkbox"/>




CUCHARA DE ARRABIO

Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek PISÉ	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 90 03/06 F	<input type="checkbox"/>	<input type="checkbox"/>




HEA

Pasek TAP	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 95 C	<input type="checkbox"/>	<input type="checkbox"/>




BOF

Pasek SLAGUN G	<input type="checkbox"/>	<input type="checkbox"/>
----------------	--------------------------	--------------------------




Metalurgia Secundaria



CUCHARA DE ACERO

Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 35 M	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 P	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 70 MGC P	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 90 F	<input type="checkbox"/>	<input type="checkbox"/>




DESGASIFICADOR RH - RH/OB


Pasek 45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 95 C	<input type="checkbox"/>	<input type="checkbox"/>

TAPAS INYECCIÓN, CAS y CONOS ESCORIA

Pasek 45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek PISÉ G	<input type="checkbox"/>	<input type="checkbox"/>





Colada Continua, Hornos de Recalentamiento y Piezas Preconformadas



TUNDISH y TAPAS DE TUNDISH

Pasek INSU 45 G	<input type="checkbox"/>	<input type="checkbox"/>
PASELITE 75	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 55 SIC 30 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 75 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 88 R	<input type="checkbox"/>	<input type="checkbox"/>



HORNOS LAMINACIÓN

Pasek INSU 15/25/45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 HR C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 C	<input type="checkbox"/>	<input type="checkbox"/>

PIEZAS PRECONFORMADAS

Corazón bóveda HEA, Snorkel RH-OB, Aros CAS-OB, Rodillos laminación, Lanzas OB



Aislantes	Aluminoso	Convencional
Gunitado / Shotcrete	Carburo de Silicio	Fast Dry
Colado / Vibrado / Manual	Magnesita	