


Primary Steelmaking


TORPEDO LADLE CAR

Pasek 80 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 S / G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 S	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 SIC 9 S	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 SIC 9 S	<input type="checkbox"/>	<input type="checkbox"/>




IRON LADLE

Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek PISÉ	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 90 03/06 F	<input type="checkbox"/>	<input type="checkbox"/>




EAF

Pasek TAP	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 95 C	<input type="checkbox"/>	<input type="checkbox"/>




BOF

Pasek SLAGUN G	<input type="checkbox"/>	<input type="checkbox"/>
----------------	--------------------------	--------------------------




Secondary Steelmaking



STEEL LADLE

Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 35 M	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 P	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 70 MGC P	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 90 F	<input type="checkbox"/>	<input type="checkbox"/>





RH - RH/OB DEGASSER


Pasek 45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 95 C	<input type="checkbox"/>	<input type="checkbox"/>

LADLE COVER (TN Process), CAS Snorkel & SLAG LADLE

Pasek 45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 85 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 AND G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek PISÉ G	<input type="checkbox"/>	<input type="checkbox"/>





Continuous casting, Reheating furnaces & Precast shapes



TUNDISH & TUNDISH COVER

Pasek INSU 45 G	<input type="checkbox"/>	<input type="checkbox"/>
PASELITE 75	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 65 AND C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 55 SIC 30 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 75 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 88 R	<input type="checkbox"/>	<input type="checkbox"/>



REHEATING FURNACES

Pasek INSU 15/25/45 G	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek 80 HR C	<input type="checkbox"/>	<input type="checkbox"/>
Pasek FD 85 C	<input type="checkbox"/>	<input type="checkbox"/>

PRECAST SHAPES

EAF Roof Deltas, RH & CAS Snorkels, OB Lances, Rolling Mills



Insulating	Aluminous Castable	Conventional Castable
Gunning / Shotcrete Castable	Silicon Carbide Cast.	Fast Dry Castable
	Magnesite Cast. / Mixes	